

Gieß = Zettel. No. I.

Zu einem Centner Cicero Fraktur
oder Schwabacher.

A	100	a	1200	ch	760
B	90	b	600	ck	150
C	90	c	50	ft	400
D	100	d	1200	ff	250
E	120	e	4100	fi	50
F	90	f	400	ff	60
G	120	ff	200	ß	200
H	120	g	700	h	200
I	120	h	600	ll	150
K	120	i	1900	j	100
L	100	k	350	ä	250
M	100	l	800	ö	200
N	100	m	800	ü	350
O	100	n	2800	.	450
P	100	o	700	,	750
Q	20	p	200	=	400
R	100	q	50	:	100
S	160	r	1700	;	100
T	100	z	50	!	50
U	100	f	600	?	50
V	100	ff	200	'	50
W	90	s	600	*	50
X	40	t	1500	+	50
Y	40	u	1200	\$	50
Z	80	v	350	(200
		w	500	[50
		x	50		
		y	200		
		ß	400		

Spatia 6000. Halbgevierte 600. Gevierte 300.

(Wörterb. d. Buchdruckerk.)

Gieß = Zettel. No. II.

Auf einen Centner Petit Fraktur und
Schwabacher.

A	200	a	2300	ch	1400	1	200
B	160	b	800	ck	250	2	200
C	180	c	100	ft	800	3	160
D	200	d	2000	fi	600	4	160
E	250	e	8000	ff	100	5	160
F	160	f	600	ff	100	6	160
G	240	ff	250	ß	300	7	160
H	240	g	1000	h	300	8	160
I	240	h	1000	ll	300	9	160
K	200	i	3200	j	300	0	200
L	200	k	450	ä	400		
M	180	l	1400	ö	350		
N	180	m	1600	ü	400	Spatia	
O	200	n	5000	.	1000	10000	
P	200	o	2000	,	1600		
Q	100	p	400	=	1000	Halbge-	
R	200	q	100	:	200	vierte	
S	260	r	3400	;	100	1000	
T	200	z	100	!	100		
U	200	f	1200	?	100	Geviert.	
V	200	ff	300	(150	800	
W	200	s	1100	,			
X	100	t	3400	†	150		
Y	100	u	2500	†	50		
Z	150	v	600	*	50		
		w	1000	\$	50		
		x	100	[50		
		y	300				
		ß	500				



Gieß-Zettel. III.

Auf einen Centner Tertia Fraktur oder Schwabacher.

A	40	a	450	ch	280	1	60
B	30	b	200	cl	50	2	40
C	30	c	50	st	140	3	40
D	40	d	400	ff	80	4	45
E	45	e	1300	ff	30	5	45
F	30	f	130	ff	30	6	45
G	40	ff	60	ff	90	7	45
H	40	g	230	ff	80	8	45
I	45	h	200	ff	60	9	40
K	40	i	600	ff	50	o	60
L	30	l	130	ä	100	Spatia 2000	
M	35	l	280	ö	80	Halbgevierte 250	
N	35	m	300	ü	130	Gevierte 180	
O	35	n	900	.	170		
P	30	o	350	,	250		
Q	15	p	70	=	160		
R	40	q	30	:	40		
S	55	r	600	?	30		
T	35	r	30	;	40		
U	35	f	200	!	30		
V	40	ff	70	(60		
W	35	s	200	,	60		
X	20	t	550	†	30		
Y	20	u	450	*	30		
Z	30	v	130	§	30		
		w	170	[30		
		x	30				
		y	70				
		z	140				

Gieß-Zettel. IV.

Auf einen Centner Batmond Fraktur oder Schwabacher.

A	135	a	1300	ch	890	1	270
B	100	b	533	cl	165	2	290
C	135	c	100	st	450	3	180
D	225	d	1100	ff	350	4	170
E	180	e	5340	ff	138	5	170
F	135	f	400	ff	180	6	135
G	235	ff	135	ff	350	7	135
H	225	g	745	ff	180	8	135
I	225	h	750	ff	215	9	135
K	116	i	2070	ff	135	o	185
L	135	l	335	ä	225	Spatia 5350	
M	135	l	800	ö	185	Halbgevierte 1100	
N	135	m	800	ü	270	Gevierte 600	
O	160	n	3100	.	670		
P	135	o	1200	,	1135		
Q	20	p	220	=	485		
R	135	q	45	:	138		
S	225	r	1920	?	138		
T	135	r	25	;	138		
U	110	f	800	!	70		
V	180	ff	350	(100		
W	180	s	625	,	50		
X	25	t	1600	†	50		
Y	30	u	1335	§	50		
Z	90	v	345	[100		
		w	400		50		
		x	45				
		y	135				
		z	330				

Gieß-Zettel. V.

Auf einen Centner Cicero Antiqua.

A	150	a	1000	st	200	ä	100
B	110	b	300	ff	200	ë	50
C	125	c	560	ff	100	ï	50
D	130	d	600	ff	100	ö	100
E	130	e	1400	ff	100	ù	100
F	110	f	250	ff	50	.	500
G	115	ff	150	ff	40	,	650
H	115	g	350	ff	200	-	500
I	250	h	300	ff	300	;	100
K	50	i	2000	ff	200	:	100
L	120	k	140	ff	200	?	50
M	120	l	600	ff	200	!	50
N	110	m	600	ff	60	(100
O	115	n	1300	ff	50	§	50
P	120	o	900	ff	50	,	100
Q	100	p	450	ff	50	*	100
R	120	q	300	ff	50	†	50
S	140	r	1000	ff	50	1	150
T	120	f	450	ff	50	2	120
U	100	ff	150	ff	50	3	120
V	150	s	450	ff	50	4	110
W	30	t	1000	ff	80	5	110
X	150	u	900	ff	50	6	110
Y	40	v	300	ff	50	7	120
Z	40	w	50	ff	50	8	110
Æ	50	x	200	ff	50	9	100
J	80	y	150	ff	50	o	150
		z	150	ff	50		

Spatia 5000. Halbgevierte 500. Gevierte 300.



Gieß-Zettel.

vi.

Auf einen Centner Mittel Fraktur oder Schwabacher.

A	70	a	800	ch	500	1	100
B	60	b	400	ck	100	2	90
C	60	c	30	ff	270	3	90
D	70	d	800	fi	120	4	80
E	90	e	2800	ff	30	5	80
F	60	f	230	ff	40	6	80
G	80	ff	80	ff	170	7	90
H	80	gh	460	ff	170	8	80
I	80	g	400	ff	100	9	80
K	80	i	1240	j	90	0	100
L	70	k	220	ä	180	Spatia	
M	70	l	480	ä	170	4000	
N	70	m	470	ü	230	Halbge-	
O	70	n	1840	.	320	vierte	
P	70	o	640	.	500	450	
Q	10	p	170	=	270	Sewiert.	
R	70	q	60	:	80	220	
S	120	r	1200	?	40		
T	70	z	40	;	80		
U	70	f	400	!	30		
V	70	ff	170	(160		
W	70	s	400	,	40		
X	30	t	1000	†	30		
Y	30	u	800	*	30		
Z	60	v	230	\$	30		
		w	380	[30		
		x	20				
		y	170				
		z	280				

Gieß-Zettel.

vii.

Auf einen Centner Text Fraktur oder Schwabacher.

A	65	a	650	ch	460	1	160
B	50	b	275	ck	80	2	170
C	65	c	50	ff	225	3	90
D	112	d	650	fi	175	4	80
E	70	e	2750	ff	170	5	80
F	65	f	200	ff	90	6	75
G	116	ff	65	ff	175	7	75
H	112	gh	370	ff	90	8	75
I	112	g	270	ff	110	9	75
K	60	i	1050	j	80	0	80
L	65	k	270	ä	110	Spatia	
M	65	l	400	ä	125	2500	
N	65	m	400	ü	140	Halbge-	
O	65	n	1550	.	350	vierte	
P	65	o	600	.	600	550	
Q	10	p	110	,	250	Sewierte	
R	65	q	25	:	75	300	
S	112	r	960	;	75		
T	65	z	25	!	75		
U	55	f	400	?	75		
V	70	ff	175	*	50		
W	70	s	310	†	50		
X	10	t	800	\$	50		
Y	10	u	660	(75		
Z	50	v	175	[50		
		w	200				
		x	25				
		y	75				
		z	175				

Gieß-Zettel.

viii.

Auf einen Centner Tertä Antiqua.

A	60	a	340	ff	90	a	40
B	50	b	100	fi	80	e	25
C	60	c	190	fi	50	y	25
D	50	d	200	ff	40	ö	40
E	65	e	580	ff	50	ü	40
F	55	f	90	ff	50	.	300
G	40	ff	50	ff	40	,	340
H	50	gh	120	ff	40	-	200
I	90	g	100	ff	60	:	30
K	30	h	700	ff	120	;	40
L	50	i	50	ff	70	?	30
M	55	k	200	ff	70	!	30
N	50	l	200	ff	70	(50
O	50	m	200	ff	40	\$	30
P	45	n	440	ff	40	,	60
Q	40	o	300	ff	30	*	30
R	60	p	150	ff	30	†	30
S	70	q	100	ff	40	1	60
T	70	r	350	ff	30	2	40
U	50	f	100	ff	40	3	40
V	40	ff	50	ff	30	4	45
W	70	s	200	ff	30	5	45
X	20	t	340	ff	30	6	45
Y	60	u	300	ff	20	7	45
Z	20	v	100	ff		8	45
Æ	10	w	30	ff		9	45
J	30	x	80	ff		0	40
		y	50	ff			60
		z	60	ff			

Spatia 2000. Halbgevierte 250. Sewierte 180.

1878

1878

1878



Gieß = Zettel.

IX.

Auf einem Centner Mittel Antiqua
oder Cursiv.

A	100	a	670	ft	170	.	320
B	80	b	200	fi	140	,	500
C	100	c	390	ff	60	-	380
D	110	d	420	fl	60	:	60
E	110	e	960	j	120	?	30
F	70	f	200	ä	80	!	30
G	70	ff	100	é	200	(120
H	70	g	270	í	80	\$	30
I	180	h	210	ó	80	*	70
K	25	i	1380	ó	80	*	60
L	80	k	100	à	40	†	30
M	80	l	450	è	30	1	100
N	70	m	400	ì	30	2	90
O	80	n	840	ò	30	3	90
P	80	o	600	ù	30	4	80
Q	60	p	300	â	20	5	80
R	80	q	200	ê	30	6	80
S	100	r	670	í	30	7	80
T	80	ff	200	ò	20	8	80
U	70	f	100	ú	20	9	80
V	100	s	350	â	75	o	100
W	20	t	670	ä	30	Spatia	3700
X	100	u	600	é	20	Halbge-	vierte
Y	20	v	200	í	70	350	
Z	60	w	30	ö	70	Gewirt.	250
J	20	x	140	ü	70		
Æ	30	y	100				
		z	100				

Gieß = Zettel.

X.

Auf einen Centner Garmond Antiqua
oder Cursiv.

A	150	a	1750	ft	350	.	950
B	120	b	400	fi	175	,	1150
C	120	c	600	ff	90	-	450
D	150	d	700	fl	56	:	125
E	150	e	2500	j	175	;	125
F	120	f	350	ç	150	!	125
G	120	ff	130	á	125	?	100
H	120	g	525	è	350	\$	113
I	238	h	400	í	90	(250
K	40	i	3000	ó	90	†	36
L	120	k	100	ó	90	*	63
M	120	l	1050	à	66	,	350
N	120	m	1050	è	112	1	175
O	120	n	2450	ì	58	2	150
P	108	o	1150	ò	58	3	120
Q	108	p	550	ù	58	4	120
R	120	q	400	â	58	5	120
S	150	r	1500	ê	58	6	120
T	120	s	1800	í	58	7	120
U	108	f	1500	ò	58	8	120
V	150	ff	250	ú	58	9	120
W	38	t	1150	â	58	o	175
X	100	u	1150	ä	58	Spatia	6500
Y	58	v	475	é	58	Halbge-	vierte
Z	38	w	75	í	58	1000	
J	88	x	350	ö	58	Gewirt.	650
Æ	40	y	250	ü	58		
		z	75				

Gieß = Zettel.

XI.

Auf einen Centner Petit Antiqua
oder Cursiv.

A	200	a	2333	ft	466	.	1200
B	160	b	533	fi	233	,	1533
C	160	c	800	ff	120	-	600
D	200	d	933	fl	75	:	167
E	200	e	3333	j	233	;	167
F	160	f	466	ç	133	!	167
G	160	ff	200	á	166	?	133
H	160	g	700	è	466	\$	148
I	318	h	533	í	100	(333
K	54	i	4000	ó	100	†	84
L	160	k	85	ó	100	*	84
M	160	l	1400	à	80	,	466
N	160	m	1400	è	150	1	233
O	160	n	3266	ì	78	2	200
P	144	o	1533	ò	78	3	160
Q	144	p	733	ù	78	4	160
R	160	q	533	â	78	5	160
S	200	r	2000	ê	78	6	160
T	160	s	2400	í	78	7	160
U	144	f	2000	ò	78	8	160
V	200	ff	333	ú	78	9	160
W	50	t	1500	â	78	o	233
X	133	u	1533	ä	78	Spatia	8668
Y	78	v	633	é	78	Halbge-	vierte
Z	50	w	100	í	78	1333	
J	120	x	466	ö	78	Gewirt.	866
Æ	45	y	333	ü	78		
		z	100				



Gieß = Zettel. Nro. XII.

Auf einen Centner Text Antiqua oder Cursiv.

A	50	a	350	ff	80	ä	30
B	50	b	150	fi	60	ë	20
C	50	c	200	fi	30	i	20
D	70	d	300	ff	30	ö	30
E	70	e	500	ff	25	ü	30
F	50	f	200	ff	25	.	300
G	50	ff	50	ff	25	,	250
H	70	gh	150	ff	20	-	200
I	80	h	200	ff	20	;	40
K	40	i	600	ff	20	!	30
L	80	k	40	ff	20	(30
M	70	l	250	ff	20	§	30
N	70	m	250	ff	20	ä	20
O	70	n	400	ff	25	è	20
P	70	o	360	ff	20	ì	60
Q	50	p	200	ff	20	ò	25
R	80	qr	200	ff	20	ù	25
S	70	r	450	ff	30	â	25
T	70	rf	200	ff	30	ê	60
U	70	s	60	ff	30	î	50
V	80	t	200	ff	30	ô	50
W	25	u	450	ff	30	û	50
X	25	v	350	ff	20	ç	50
Y	25	w	200	ff	20		50
Z	30	x	30	ff	20		50
Æ	25	y	80	ff	20		50
J	25	z	70	ff	20		50

Spatia 1500. Halbgevierte 300. Gevierte 150.

(Wörterb. d. Buchdruckerf.)

Gieß = Zettel. Nro. XIII.

Auf einen Centner Perl Fraktur oder Schwabacher.

A	350	a	3000	ch	1900	1	600
B	310	b	1250	ch	450	2	500
C	280	c	300	ff	1200	3	400
D	500	d	2500	ff	800	4	380
E	400	e	12000	ff	350	5	400
F	280	f	900	ff	300	6	400
G	480	ff	350	ff	800	7	380
H	480	gh	1650	ff	400	8	380
I	500	h	1600	ff	500	9	400
K	300	i	4500	ff	600	0	600
L	300	l	700	ff	800		
M	350	l	1800	ff	600		
N	320	m	2000	ff	600		
O	380	n	6400	ff	1500	Spatia	12500
P	300	o	2000	ff	2400	Halbgevierte	2400
Q	50	p	600	ff	900	Gevierte	1100
R	360	q	150	ff	300		
S	560	r	4200	ff	250		
T	300	r	150	ff	75		
U	280	s	1600	ff	180		
V	400	ff	700	ff	400		
W	450	s	1300	ff	120		
X	50	t	3600	ff	120		
Y	150	u	3000	ff	180		
Z	250	v	800	ff	400		
		w	1000	ff	200		
		x	80	ff			
		y	500	ff			
		z	800	ff			

Gieß = Zettel. Nro. XIV.

Auf einen Centner Perl Antiqua oder Cursiv.

A	300	a	3500	ff	700	.	1900
B	240	b	800	ff	330	,	2300
C	240	c	1200	ff	180	-	900
D	300	d	1400	ff	120	:	250
E	300	e	5000	ff	330	?	200
F	240	f	700	ff	250	!	250
G	240	ff	300	ff	700	(500
H	240	gh	1050	ff	180	§	230
I	480	h	800	ff	180	*	700
K	80	i	6000	ff	180	†	130
L	240	k	130	ff	120	†	130
M	240	l	2100	ff	224	†	330
N	240	m	2100	ff	116	1	300
O	240	n	4900	ff	116	2	240
P	216	o	2300	ff	116	3	240
Q	216	p	700	ff	116	4	240
R	240	q	800	ff	116	5	240
S	300	r	3000	ff	116	6	240
T	240	f	2000	ff	116	7	240
U	216	ff	500	ff	116	8	240
V	300	s	3600	ff	116	9	240
W	70	t	3000	ff	116	0	330
X	200	u	2500	ff	116	Spatia	13000
Y	116	v	950	ff	116	Halbgevierte	2000
Z	80	w	200	ff	120	Gevierte	2000
Æ	50	x	1100	ff	120		1300
		y	500	ff			
		z	200	ff			

